


Getting High Equipment Reliability

By

Mike Sondalini

www.lifetime-reliability.com


High Reliability is a choice you make




Value of reliability on operating time

“Time is Money” – *Benjamin Franklin*


MTBF - average time between failures




Value of reliability on Unit Cost of Production



$$\text{Unit Cost of Production } (\$/T) = \frac{\text{Operating Costs in the Period } (\$)}{\text{Total Saleable Throughput (Tonne)}}$$




Your machines are components in series




Electric motor drive end bearing

Series arrangements are at high risk



*Motor parts
shown as a
series*




*“Any one
part fails;
all fails”*

Here is why clean lubricant is so important: It gets between the parts in your machines!

Calculating series reliability

Reliability is the **chance** that an item will last long enough to do its duty



$$R_{\text{series}} = R_1 \times R_2 \times R_3 \times \dots \times R_n$$

$$R_{\text{series}} = 0.99 \times 0.99 \times 0.99 \times 0.99 \times 0.99 \times 0.99 \times 0.99 \times 0.99 = (0.99)^9 = 0.91 \text{ (or 91\%)}$$

$$R_{\text{series}} = 0.99 \times 0.99 \times 0.99 \times 0.99 \times 0.5 \times 0.99 \times 0.5 \times 0.99 \times 0.99 = 0.23$$


“Any poor, all poor”

$$R_{\text{series}} = 0.99 \times 0.99 \times 0.99 \times 0.99 \times 0 \times 0.99 \times 0 \times 0.99 \times 0.99 = 0$$

“Any fails, all fails”


But where do your failures start?

Your problems start with chance variation...




What chance variation does to machines

High Vibration:




Deformation:




Extract from 'Shaft Alignment Handbook', Piotrowski

Misalignment:

IR Image After Alignment



IR Image Before Alignment




Fastener Torque Error:




Unclean Lubricant:




Unbalance:




Cause and effect of your equipment failures




Cause: Incorrect Processes
(controlled by management)




Cause: Induced Stress
(controlled by people)




Cause: Accumulated Fatigue
(controlled by people)





The secret is to control variability to within the limits that bring benefits



Understanding what it means to be 'in control and capable'



Work is a series process of tasks



$$R_{\text{series}} = R_1 \times R_2 \times R_3 \dots$$

What is the chance that the whole job will done right?

Risks to work quality and machine reliability

Task Reliability is the chance that a task will be performed to its required quality.



A five task job.

$$R_{\text{job}} = R_1 \times R_2 \times R_3 \times R_4 \times R_5$$



0.59

10 tasks	20 tasks	50 tasks
0.35	0.12	0.05

Complicated non-routine tasks



0.77


10 tasks	20 tasks	50 tasks
0.90	0.82	0.61




0.95

Controlling human error is the greatest challenge to reliability

Carpenter's creed: *'measure twice, cut once'*




1 error every 200 opportunities
~ 1 / wk



1 error every 5000 opportunities
~ 1 / 20 wk

The power of parallel proof-tests



$$R_{\text{system}} = 1 - [(1 - R_1) \times (1 - R_2) \times (1 - R_3) \dots]$$


$$1 - [(1 - 0.9) \times (1 - 0.99)]$$

$$1 - [0.1 \times 0.01]$$

$$1 - [0.001] = 0.999$$




Remove the variability from your business processes
– *unless you want to run your business by luck!*




In the end... reliability is a quality control issue.






Set work task standards to deliver the quality that produces the reliability you want




Equipment reliability is malleable by choice of policy and quality of practice



How do we apply it to our machines?



IR Image After Alignment



Electric motor drive end bearing


Control Your Processes by Converting your SOPs to 3T Accuracy Controlled Procedures

Task Step No.	Task Step Owner	Task Step Name (Max 3 – 4 words)	Full Description of Task (Include all tables, diagrams and pictures here)	Tolerance Range			Record Actual Result	Action if Out of Tolerance	Sign-off After Complete
				Test for Correctness	Good	Better			

Diagram annotations: A yellow arrow labeled 'Test' points to the 'Test for Correctness' column. A yellow arrow labeled 'Tolerance' points to the 'Tolerance Range' columns. A yellow arrow labeled 'Target' points to the 'Best' column. A pink arrow labeled 'Continual improvement' points from the 'Full Description of Task' column towards the 'Tolerance Range' columns. Two pink arrows point from the 'Better' and 'Best' columns back towards the 'Tolerance Range' header.


- Specify the 3Ts (Target, Tolerance, Test) for task precision and accuracy
- Describe in a measurable fashion what 'good', 'better' and 'best' are to challenge people to strive for excellence
- Advise what to do when out of tolerance – i.e. when not 'it's good enough'
- Get a signature when 3T done to tolerance so people are committed to precision
- Drive continual improvement by regularly introducing an even more precise 'best'

Use condition monitoring as the proof test for task quality



Life Extension Zone

Failure Elimination Zone



Getting high equipment reliability...

