



# Reliability Centred Maintenance Introduction and Overview

## Online Distance Education Course Workbook

Presented by  
Lifetime Reliability Solutions

PO Box 2091,  
ROSSMOYNE, WA, 6184  
AUSTRALIA

Phone: +61 (0) 402 731 563  
Fax: +61 (8) 9457 8642

Email: [info@lifetime-reliability.com](mailto:info@lifetime-reliability.com)  
Website: [www.lifetime-reliability.com](http://www.lifetime-reliability.com)

# CONTENT

Help from the DOCTOR.....	3
Activity 1 – Equipment Criticality Analysis.....	7
Basic Business Risk Matrix .....	8
Risk Identification and Analysis - Template 1.....	9
Risk Treatment Schedule and Action Plan - Template 2 .....	10
Activity 2a – Basic FMEA/RCM System Level.....	11
Activity 2b – Basic FMEA/RCM Component Level.....	14
Example Check Valve ‘C’ Failure Effect Consequence Table.....	16
Activity 3 – Flow Valve Failure Effect Consequence Table .....	17
Activity 4 – Identify Hidden Failures .....	20
Activity 5 – Maintenance Strategy Selection.....	21
Maintenance Strategy and Maintenance Task Table .....	22
Case Study 1: Reliability Centered Maintenance for Turbines.....	23
Case Study 2: Confirming Effectiveness of Maintenance Task .....	26
Case Study 3: Motorised Gate Valve RCM Extract – Failure Cause Effect Symptom .....	31
Case Study 3: Motorised Gate Valve RCM Extract – Maintenance Strategy Selection.....	32
Activity 6 – Maintenance Activity Effectiveness .....	33
The Human Factor .....	34
Activity 7 – Standardised Maintenance Procedure with ACE 3Ts.....	36
Activity 8 – RCM Process Plant and Select Operating / Maintenance Strategy.....	39
Failure Effects Consequence and Failure Symptom Analysis Table .....	40
Maintenance Strategy and Maintenance Task Table .....	41
Activity 9 – Reliability Growth Cause Analysis.....	42
Example Reliability Growth Cause Analysis (RGCA).....	46
Summary Table of Reliability Growth Cause Analysis Plan.....	50
Case Study 4: Implementing RCM in the Mining Industry .....	51
Table of the Journey to Reliability and Maintenance Mastery .....	52
Making Your Organisation an ACE.....	53
Example ACE 3T – Flange Connection Procedure with Tolerance Banding.....	54
Activity 10 – Take-Home Plan to Use RCM for Improving Reliability.....	59