

Planned Preventive Maintenance Program Course Workbook and Reference Materials

CONTENTS

| | |
|--|----|
| Extracts on the Causes of Equipment Failure | 2 |
| Activity 2 – FMEA System Level..... | 3 |
| Activity 2 (alternative) – FMEA Component Level | 5 |
| Activity 3 – Costing Failure Consequences | 7 |
| Tables for Calculating the Defect and Failure Total Cost | 13 |
| Activity 4 – Equipment Criticality..... | 17 |
| Risk Assessment Matrix..... | 20 |
| Risk Identification and Analysis – Template 1 | 21 |
| Risk Treatment Schedule and Action Plan – Template 2 | 22 |
| Activity 5 – CIP Circuit Criticality | 23 |
| Activity 6 – CIP Circuit Maintenance Strategy Selection | 25 |
| Activity 8 – Develop CIP Supply Pump Preventive Maintenance Strategy | 26 |
| Activity 9 – Bending and Torsional Stress in Steel Parts | 27 |
| Activity 10 – Improve Procedures with Inspection and Test Plan Standards | 28 |
| Set Reliability Standards for Pump Set Equipment | 31 |
| Activity 11 – Confirm Operating and Maintenance Strategy Selection do Reduce Operating Risk .. | 34 |